UPDATED WEBBOAT 4G PLUS APP
AVAILABLE ON THE APP STORE
& NEW IT1004PLUS FIRMWARE

The updated WEBBOAT 4G PLUS App for the iOS devices (v 1.3) is available on the App Store

http://apple.co/2aA4lSf

with major improvements for the users.
In detail:

1. **WiFi instability fix**
2. **UI automatic refresh**
3. **WiFi and Mobile additional network details**

After the App update, it is highly recommended to reset the unit by pressing the Options icon (1), then RESET Router (2) and then OK.

Wait 1 minute, disable and enable the WiFi connection on your device and reconnect to the Glomex_weBBoat network.

Open again the App and follow the weBBoat's configuration wizard.

You do not need the firmware update for using the weBBoat 4G Plus App version 1.3

NEW IT1004PLUS FIRMWARE
IT1005_R_10.02.116_WEBUI.bin

The new firmware optimizes the IT1004PLUS WiFi's performances, it is recommended to update the unit by downloading the new firmware and update instructions on:

http://bit.ly/2axLkEL

**You do not need the firmware update for using
the weBBoat 4G Plus App version 1.3**